


Continuous Improvement using Statistical Process Control

A Training Course
for
Forest Products Manufacturers

by

Timothy M. Young
Associate Professor



The University of Tennessee
Forest Products Center
2506 Jacob Drive
Knoxville, TN 37996-4570
865.946.1119
tmyoung1@utk.edu
<http://www.spcforwood.com>



The University of Tennessee Forest Products Center is located on the Agricultural campus in Knoxville, Tennessee. The Center is housed in the Department of Forestry, Wildlife and Fisheries and functions under the research mission of the Institute of Agriculture Experiment Station.

The mission of the Forest Products Center is to solve problems for forest products producers and provide leadership in research and education to ensure future competitiveness and sustainability of the industry. The Center is focused on providing research and education for the forest products industry in Tennessee, the region, and beyond.

The Tennessee Agricultural Experiment Station conducts mission oriented research programs to serve Tennessee agriculture and forestry producers. The Center is an outgrowth of the Governor's Council on Agriculture and Forestry, convened in May 1996. The Center is the only such full-time research facility among U.S. university programs. Undergraduate and graduate students are included in the research programming of the Center and gain valuable experience in conducting research.



Gage R&R Exercise



Modern Training Facility and
Small Class Size

Contents

	<u>Page</u>
1. Introduction to Continuous Improvement	7
<i>A. Foundations for Successful Continuous Improvement</i>	8
<i>B. Deming's Views and Influences</i>	10
<i>C. Identifying Key Process Variables & Product Attributes</i>	15
<i>D. Linking Key Process Variables with Critical Product Attributes</i>	17
2. Introduction to <u>S</u> tatistical <u>P</u> rocess <u>C</u> ontrol (SPC)	18
<i>A. Definition of SPC</i>	19
<i>B. The Engineering Concept of Variation</i>	20
<i>C. The Shewhart Concept of Variation</i>	21
3. Understanding Natural Variation	24
<i>A. Deming's "Red Bead Box" Experiment</i>	25
<i>B. The Basic Idea of the Shewhart Control Chart in Manufacturing</i>	31
<i>C. Sources of Variation</i>	32
4. Control Charts in Manufacturing	33
<i>A. Sampling Manufacturing Processes</i>	34
<i>B. Measurement Data</i>	44
<i>C. Attribute Data</i>	45
5. Statistics and Math Review	46
<i>A. Statistics that Measure Location</i>	
<i>i. Average, Median and Mode</i>	47
<i>B. Statistics that Measure Dispersion of Variation</i>	
<i>i. Range, Sample Variance and Sample Standard Deviation</i>	51
<i>C. Viewing Location and Dispersion using the Histogram</i>	54

Contents

Page

5. Statistics and Math Review	
<i>D. The Central Limit Theorem</i>	57
<i>E. Graphical Summaries</i>	62
6. Control Charts for Measurement Data	63
A. <i>Control Charts without Subgrouping</i>	64
i. <i>X-Individual and Moving Range Charts</i>	64
- <i>Example of X-Individual and Moving Range Chart</i>	65
B. <i>Control Charts with Subgrouping</i>	73
i. <i>X-bar and R Chart</i>	74
- <i>Example of X-Bar and R Chart</i>	78
iii. <i>X-bar and s Charts</i>	84
7. Control Charts for Attribute Data	87
A. <i>Charts for Nonconforming Units</i>	89
i. <i>np Chart</i>	91
ii. <i>p Chart</i>	94
B. <i>Charts for Nonconformities</i>	97
i. <i>c Chart</i>	98
ii. <i>u Chart</i>	101
8. “Run-Rules” for Control Charts	105
9. Analyzing “Special-Cause” Variation	108
A. <i>Pareto Chart</i>	109
B. <i>“Fish-Bone” or Ishikawa Diagram</i>	111
10. Correlation Statistics for Linear Relationships	114

Contents

Page

11.	“Plan-Do-Check-Act” Cycle	136
12.	Team Assignments	139
13.	Process Flow Diagrams	144
	A. Example 1. MDF Manufacture	147
	B. Example 2. Hardboard Manufacture	152
14.	Process Capability	158
	A. Definition	159
	B. Standardized Formula	160
	C. The C_p Index	161
	D. The C_{pk} Index	162
	E. The C_{pm} Index	163
	F. Example	164
	G. Estimating Process Capability from Control Chart	165
	H. Statistical Tolerancing	167
15.	Taguchi Loss Function	182
16.	Components of Variance	189
	A. Total Variation	190
	B. Estimating “Within-Batch” Variation	192
	C. Estimating “Between-Batch” Variation	192
	D. Exercise	193
	E. Independent Exercise	201
17.	An Introduction to Six Sigma Quality	207

Contents

Page

18.	Team Assignment Presentations	218
19.	Deming's " <i>Funnel Experiment</i> "	223
	A. Rule 1	226
	B. Rule 2	227
	C. Rule 3	228
	D. Rule 4	229
20.	Assessment	230
21.	Review of Assessment	238
22.	Review of Key Concepts	244
23.	Gauge R&R Studies	245
 <u>Advanced Statistical Methods:</u>		
24.	Difference Charts	270
25.	Control Charts for Autocorrelated Data	274